

## Tested cameras by IVS

(2018.02.21.)

Vendor	Model	Firmware	Supported	IVS version
ACTi	B97-A	A1D-500-V6.08.30-AC	Yes	3.0.5.3
ACTi	D72A-A	A1D-500-V6.08.30-AC	Yes	3.0.5.3
ACTi	E95-A	A1D-500-V6.08.30-AC	Yes	3.0.5.3
ACTi	I51	A1D-500-V6.08.30-AC	Yes	3.0.5.3
ACTi	I71	A1D-500-V6.08.30-AC	Yes	3.0.5.3
Appro Technology Inc.	LC-7411	2.02		
Arecont	AV2105DN	65144	No (only RTSP)	2.7.1.1
ARH	FreeWay	V3.1.2.25	Yes	3.1.2.10
ARH	ParkIT (1.3 Mp)	V3.1.2.8	Yes	3.0.0.5
ARH	ParkIT (WVGA)	V3.1.2.8	Yes	3.0.0.5
ASB	ASB-W986AE-V1		Yes	3.0.2.10
Avigilon	2.0-H3M-DO1	2.6.0.92 build 13177	yes	3.1.2.10
Avigilon	2.0MP-HD-H264-B1	2.2.0.14(7496)	No (only RTSP)	2.2
Avigilon	5.0-H3-B2	2.4.6.30(8448)	Yes	2.7.1.1
AVTech	AVM328A	1051-1027-1035-1008	No (only RTSP)	2.7.1.3
AVTech	AVM357A	1073-1029-1045-1008	yes	4.1.0.2
AVTech	AVM457A	1023-1007-1016-1003	No (only RTSP)	2.7.1.3
AVTech	AVM459	1026-1007-1018-1003	No (only RTSP)	2.7.1.3
AVTech	AVM552BP/F28F12	1058-1025-1031-1014	Yes	3.0.3.2
AVTech	AVM571	1021-1013-1013-1010	No (only RTSP)	2.7.1.3
Axis	232D+	4.47.1	yes	3.2.0.4
Axis	AXIS P5624-E Mk II	6.50.1.2	yes	4.2.1.1
Axis	AXIS P5624-E Mk II	7.20.1	yes	4.2.1.1
Axis	AXIS P5624-E Mk II	7.30.1	yes	4.2.1.1
Axis	M1013	5.40.5.1	Yes*	
Axis	M1014	5.40.5.1	Yes	
Axis	M1033-W	5.40.5.1	Yes*	
Axis	M1034-W	5.40.5.1	Yes*	
Axis	M1054	5.40.9.2	Yes*	
Axis	M1103	5.40.9.2	Yes*	
Axis	M1104	5.40.9.2	Yes*	

Vendor	Model	Firmware	Supported	IVS version
Axis	M1113	5.40.9.2	Yes*	
Axis	M1113-E	5.40.9.2	Yes*	
Axis	M1114	5.40.9.2	Yes*	
Axis	M1114-E	5.40.9.2	Yes*	
Axis	M2014-E	5.40.12	Yes*	2.6
Axis	M3007	5.40.13.1	Yes	2.8.0.4
Axis	M3014	5.40.9.2	Yes*	
Axis	M3113-R	5.40.9.2	Yes*	
Axis	M3113-VE	5.40.9.2	Yes*	
Axis	M3114-R	5.40.9.2	Yes*	
Axis	M3114-VE	5.40.9.2	Yes*	
Axis	M3203	5.40.9.2	Yes*	
Axis	M3203-V	5.40.9.2	Yes*	
Axis	M3204	5.40.9.2	Yes*	
Axis	M3204-V	5.40.9.2	Yes*	
Axis	P1343	5.40.9.2	Yes*	
Axis	P1343-E	5.40.9.2	Yes*	
Axis	P1344	5.22.2	Yes	
Axis	P1344	5.40.9.2	Yes	
Axis	P1344-E	5.40.9.2	Yes*	
Axis	P1346	5.40.9.2	Yes*	
Axis	P1346-E	5.40.9.2	Yes*	
Axis	P1347	5.40.9.2	Yes*	
Axis	P1347-E	5.40.9.2	Yes*	
Axis	P3301	5.40.9.2	Yes*	
Axis	P3301-V	5.40.9.2	Yes*	
Axis	P3304	5.40.9.2	Yes*	
Axis	P3304-V	5.40.9.2	Yes*	
Axis	P3343	5.40.9.2	Yes*	
Axis	P3343-V	5.40.9.2	Yes*	
Axis	P3343-VE	5.40.9.2	Yes*	
Axis	P3344	5.40.9.2	Yes*	
Axis	P3344-V	5.40.9.2	Yes*	
Axis	P3344-VE	5.40.9.2	Yes*	
Axis	P3346	5.40.9.2	Yes*	
Axis	P3346-V	5.40.9.2	Yes*	
Axis	P3346-VE	5.40.9.2	Yes*	
Axis	P5532	5.40.9.2	Yes*	

Vendor	Model	Firmware	Supported	IVS version
Axis	P5532-E	5.40.9.2	Yes*	
Axis	P5534	5.40.9.2	Yes*	
Axis	P5534-E	5.40.9.2	Yes*	
Axis	P8513	5.40.9.2	Yes*	
Axis	P8514	5.40.9.2	Yes*	
AxView	ipcam000	V020110B20120225R0667T001 1	Yes	
Basler	BIP2-1280c-dn	3.14.0	No (only RTSP)	2.8.1.5
Bosch	AutoDome FullHD 7000 PTZ	NA	Yes	
Bosch	AutoDome Junior PTZ	NA	Yes	
Bosch	AutoDome SD 7000 PTZ	NA	Yes	
Bosch	Dinion capture 5000 IP	NA		
Bosch	Dinion HD 1080p D/N IVA	66500500	Yes	
Bosch	DINION HD 720p IVA	73500580	Yes	2.8.1.4
Bosch	Dinion NBN-733V-P HD 720p Startlight	NA	Yes	
Bosch	Dinion NBN-832V-P FullHD fix	NA		
Bosch	Dinion NBN-921-P	15500552	Yes	
Bosch	Dinion NBN-921-P	59500550	Yes	
Bosch	Dinion NBN-921-P	65500560	Yes	
Bosch	Dinion NBN-921-P	39500570	Yes	
Bosch	Dinion NBN-932V-IP HD 1080p HDR fix	NA		
Bosch	Dinion NER-L2	15500552	Yes	2.7.1.1
Bosch	Dinion-IP-NWC	19500410	Yes	
Bosch	FlexiDome NDC-455-P IVA	10500453		
Bosch	FlexiDome NDN-421-P	59500550	Yes	
Bosch	FlexiDome NDN-498-P	59500550	Yes	
Bosch	NBN-80052-BA (DINION IP starlight 8000 MP)	93000591	Yes	3.1.1.1
Bosch	NDC-225-PI	59500550	Yes	
Bosch	NDC-265-P	59500550	Yes	
Bosch	NDC-265-P	15500552	Yes	
Bosch	NTC-255-PI	59500550	Yes	
Bosch	VG5 AutoDome HD IVA	24500454	Yes	
Bosch	VG5 AutoDome HD IVA	07500453	Yes	
Bosch	VIP X1 XF IVA	09500453	Yes	

Vendor	Model	Firmware	Supported	IVS version
Brickcom	MD-300Ap-A1	v3.2.0.6	Yes	3.0.2.10
Brickcom	OSD-200A 20xp	gk20130710NSA	Yes	3.0.2.12
Dahua	DH-SD59230S-HN	2.210.Dahua 02.0.R, build: 2014-08-29(V4.1.1)	Yes	3.1.2.10
Dahua	IPC-HFW1320S	2.400.Dahua 00.26.R, build: 2016-02-19	yes	4.0.0.3
Dahua	IPC-HFW2200R-Z	2.420.Dahua 00.5.R, build: 2014-09-29	Yes	3.1.2.10
DynaColor	NH223	z120131126NSA	Yes	2.8.0.1
DynaColor	NH820-30F3	z120140221NSA	Yes	2.8.0.1
DynaColor	NV063	z120120530NSA	Yes	
DynaColor	NV063	z120120912NSA	Yes	
Eneo	NXD-2012PTZ1080	1.3.8-X1_release	Yes	3.0.3.1
Eneo	PXC-2080Z03	4.25-155-ds	Yes	3.0.2.12
Eneo	PXD-2018PTZ1080	vr20120614NSA	Yes	3.0.0.2
Eneo	PXD-2030PTZ1080	vr20140416NSA	Yes	3.0.2.12
EuroVideo	EVC-IP-DV806IPD2	V2.5.1.5 build 2014-08-14	Yes	3.0.4.6
EverFocus	EPN4122	1.0.16_F1	Yes	3.0.2.7
FLIR Systems	FC-313-PAL	Nexus v2.5.19.0	Yes	3.0.2.12
Grundig	GCI-H0503B	720110915NS	Yes	
HD Vidy	HDV-AIO2M	1.0.3.11	No (only RTSP)	2.2
Hikvision	DS-2CD7133-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD7153-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD733F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD733F-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD752MF-E	V2.0 build 110426	Yes	
Hikvision	DS-2CD752MF-FB	V2.0 build 110426	Yes*	
Hikvision	DS-2CD752MF-FBH	V2.0 build 110426	Yes*	
Hikvision	DS-2CD752MF-IFB	V2.0 build 110426	Yes*	
Hikvision	DS-2CD752MF-IFBH	V2.0 build 110426	Yes*	
Hikvision	DS-2CD753F-E	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD753F-E	V3.0 build 110921	Yes	
Hikvision	DS-2CD753F-EI	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD754F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD754F-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD754FWD-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD754FWD-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD762MF-FB	V2.0 build 110426	Yes*	

Vendor	Model	Firmware	Supported	IVS version
Hikvision	DS-2CD762MF-FBH	V2.0 build 110426	Yes*	
Hikvision	DS-2CD762MF-IFB	V2.0 build 110426	Yes*	
Hikvision	DS-2CD762MF-IFBH	V2.0 build 110426	Yes*	
Hikvision	DS-2CD763NF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD763NF-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD763PF-E	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD763PF-E	V3.0 build 100820	Yes	
Hikvision	DS-2CD763PF-E	V4.0.3 build 120821 Unofficial firmware!	Yes	
Hikvision	DS-2CD763PF-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD783F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793NF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793NF-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793NFWD-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793NFWD-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793PF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793PF-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793PFWD-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD793PFWD-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8133F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8153F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8253F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8253F-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8254F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD8254F-EI	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD833F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD852MF-E	V2.0 build 090629	No	
Hikvision	DS-2CD852MF-E	V2.0 build 110426	Yes*	
Hikvision	DS-2CD853F-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD854F-E	V3.0 build 101201	No (only RTSP)	2.2
Hikvision	DS-2CD854F-E	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD854F-E	V4.0.3 build 121126		
Hikvision	DS-2CD862MF-E	V2.0 build 110426	Yes*	
Hikvision	DS-2CD863NF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD863PF-E	V3.0 build 110117	No (only RTSP)	2.2
Hikvision	DS-2CD863PF-E	V4.0.3 build 120821 Unofficial firmware!	Yes	

Vendor	Model	Firmware	Supported	IVS version
Hikvision	DS-2CD863PF-E	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD876BF	V2.0 build 101102	No (only RTSP)	2.2
Hikvision	DS-2CD876MF	V2.0 build 101102	No (only RTSP)	2.2
Hikvision	DS-2CD883F-E	V3.0 build 110921	Yes	
Hikvision	DS-2CD883F-E	V4.0.1 build 120508	Yes	
Hikvision	DS-2CD886BF-E	V2.0 build 101102	No (only RTSP)	2.2
Hikvision	DS-2CD886BF-E	V2.0 100529	No	
Hikvision	DS-2CD886MF-E	V2.0 build 101102	No (only RTSP)	2.2
Hikvision	DS-2CD893NF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD893NFWD-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD893PF-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2CD893PFWD-E	V4.0.1 build 120508	Yes*	
Hikvision	DS-2DF1-514	V3.1.2 build 121124	Yes	
Hikvision	DS-2DF1-572	V4.1.6 build 130422	Yes Csak ILN- ként!	
Hikvision	DS-2DF5284-A	V5.0.4 build 130703	Yes	2.7.1.1
Hikvision	DS-2DF5286-A	V5.1.0 build 130923	Yes	2.7
Hikvision	DS-2DF7284-A	V5.1.4 build 131219	Yes	3.0.0.4
Hikvision	DS-2DF7286-AW	V5.1.4 build 131219	Yes	2.9.0.2
Hikvision	DS-2DF8836IV-AELW	V5.4.9 build 170309	yes	4.1.0.2
Hikvision	DS-6704HFI	V1.2.3, build 141203	Yes	3.1.2.10
Hikvision	DS-6704HFI	V1.1.0, build 130709	Yes	2.7.1.1
Hikvision	DS-6716HFI-SATA	V1.1.0, build 130709	Yes	2.7.1.2
IndigoVision	BX420-HD-VR-RS-IR	2.1.0	yes	4.1.0.2
JVC	VN-H37U	6.01.006	Yes	3.0.2.10
MERIT-LILIN	IPR7722E	1.0.52	No (only RTSP)	2.2
Mobotix	M15D Szenzorok: 1. b/w 6MP, L22/B041,F1.8 2. color 6MP, L22/B041,F1.8	-	yes (only on <a href="http://mjpeg">http://mjpeg</a> )	4.3.0.6
Panasonic	WV-SC384	1.46		
Panasonic	WV-SC385E	1.61	Yes	
Panasonic	WV-SF335	1.61	Yes	
RockTeco	IPC201	1.8.0.6a_201203031643	Yes	
Samsung Techwin	SNB-5000	2.10_111227	Yes	

Vendor	Model	Firmware	Supported	IVS version
Samsung Techwin	SNB-5000	2.11_120821	Yes	
Samsung Techwin	SNB-5000P	3.01_121105	Yes	2.6
Samsung Techwin	SNB-5001P	1.20_130813	Yes	2.6
Samsung Techwin	SNB-6004P	1.00_130412	Yes	2.6
Samsung Techwin	SNB-7000	1.20_111227	Yes	
Samsung Techwin	SNB-7000P	1.20_111227	Yes	2.6
Samsung Techwin	SNB-7000P	2.10_130416	Yes	2.6
Samsung Techwin	SNB-7001P	1.03_121108	Yes	2.6
Samsung Techwin	SNP-3120V	3.01_140915	Yes	3.1.2.10
Samsung Techwin	SNP-6200	1.00_120403	Yes	
Samsung Techwin	SNP-6201H	3.02_140722	Yes	3.0.5.3
Samsung Techwin	SPE-100	2.30_130820	Yes	
Shenzhen Sunell	IPR54/14ALDN/13	v1.6_build044014_148	Yes	2.7
Sony	SNC-CH120	1.12.03	Yes	
Sony	SNC-CH140	1.34.00	Yes	
Sony	SNC-CH210	1.12.00	Yes	
Sony	SNC-CH240	1.85.00	Yes	3.1.1.1
Sony	SNC-CH240	1.34.00	Yes	2.5
Sony	SNC-EP580	1.70.00	Yes	
Sony	SNC-VB600B	1.3.0	No (only RTSP)	2.2
Sony	SNC-VB600B	1.5.1	No (only RTSP)	2.2
Sony	SNC-VB630	1.4.0	No (only RTSP)	2.6
Sony	SNC-VB630	1.5.0	No (only RTSP)	2.6
Sony	SNC-VM600B	1.5.0	No (only RTSP)	2.6
Techson	TC IP E1-D 62030 IR VF MDN 2.8-12	3.4.3, build 2014.07.14.	yes	4.3.0.4
Techson	TC IP S1-Pro 52030 IR MDN	4.1	yes	4.1.0.2
Techson	TC IP T-Pro 72048 IRVF MDN 2.8-12	3.4.1, build 2014-7-31	Yes	3.1.2.10
Techson	TC IP-D 52042 IR MDN	3.4.0	Yes	3.0.2.12
Techson	TC IP-D 52042 IRVF MDN W	3.3.5, build 2014.2.26.	yes	3.1.2.10.
Techson	TCI MAO C602 IR A VF (MAOC602IAV)	4.1, build 2017.08.21.	yes	4.3.0.4
Vivotek	FD8134	FD8134-VVTK-0109a	Yes	
Vivotek	FD8134	FD8134-VVTK-0105b	Yes	
Vivotek	FD8136	(0200c) FD8136-VVTK-0200	Yes	2.8.1.7

Vendor	Model	Firmware	Supported	IVS version
Vivotek	FD8152V	FD8152-VVTK-0100	Yes	3.0.2.12
Vivotek	FD8365EHV	FD8365-VVTK-0201	Yes	3.0.2.12
Vivotek	FE8181	FE8181-VVTK-0100	Yes	3.0.2.12
Vivotek	IB8354	IB8354-VVTK-0102	Yes	3.0.2.12
Vivotek	IB9371-HT	0100	yes	3.2.1.4
Vivotek	IP7361	0201f	No (RTSP also NO)	2.8.1.7
Vivotek	IP8155HP	IP8155-VVTK-0201	Yes	3.0.2.12
Vivotek	IP8161	0107a	Yes	2.8.1.7
Vivotek	IP8165HP	IP8165-VVTK-0201	Yes	3.0.2.12
Vivotek	IP8172P	0200i	Yes	2.8.1.7
Vivotek	IP8332	(0300e) IP8332-VVTK-0300e	Yes	2.8.1.7
Vivotek	IP8335H	0204c	Yes	2.8.1.7
Vivotek	IP8355EH	IP8355-VVTK-0201	Yes	3.0.2.12
Vivotek	IP8362	(0200d) IP8362-VVTK-0200	Yes	2.8.1.7
Vivotek	IP8365EH	IP8365-VVTK-0201	Yes	3.0.2.12
Vivotek	SD8364E	SD8364-VVTK-0201	Yes	3.0.2.12
Vivotek	VC8201	VC8201-VVTK-0100	Yes	3.0.2.12
XONZ	T38F006-ONVIF-P2P (XZ-52C-F/P)	V2.5.0.0 build 2013-10-24 19:02:12	No (only RTSP)	3.0.2.10

\*: Not tested but another device with the same firmware has been tested.